CONFIDENTIAL

25 August 1959

MEMORANDEM FOR THE RECORD

SUBJECT: Visit to BMI Regarding Changes in Incinerator

- 1. On Thursday, 20 August, I visited Battelle to discuss proposed changes to be made in the incinerator presently under fabrication and assembly. These changes have some about as a result of the tests being conducted on the currently available unit.
 - 2. The changes proposed for this second incinerator are listed below:
- a. The portion of the stainless steel liner that starts to taper inward at the bettem will be welded with a beed weld completely around in order to prevent separation from the vertical wall. On the present unit this is only turned over and a large separation has developed due to the beating this incinerator has taken.
- b. A second viewing part will be incorporated at the top, about 90° from the present viewing port, around past the door.
- c. A step, for short people to stand on, will be provided for looking into the viewing port. It will consist of an eight inch high steel that will hook onto brackets that will be welded onto the air duct.
- d. The two belts at the bottom of the duct (from the blower to the chamber) will be eliminated. The flange, where the connection is made, will be beefed up. This will allow for belts to be placed six inches apart rather than the two inches now being used.
- e. The V-band flange will be made heavier for connection of the stack to the incinerator proper.
- f. A longer handle for regulating the air will be provided to incorporate a mechanical interlock system with the door to prevent opening of the door while the air system is on.
- g. If possible something will be done about the linerast the doorway in order to provide a more even entrance.
- h. The radiation shield will be made to go 360° around the stack rather than the present 180° .



25X1

25X1



- i. "Open" and "Closed" will be stencilled on top of th air duct for use with the air valve.
 - j. Improvement of the damper stop mechanism will be made.
- k. If possible tests will be conducted on a new idea for a collector system for the effluents.
- 3. During the discussions the size of the rtack was kicked around. It was learned that in order to reduce the diameter of the stack from sixteen inches to fourteen inches an additional 1 HP would have to be added to the motor.
- 4. Development of a smaller size version of this incinerator system was also discussed. If each of the dimensions of the present incinerator were reduced by 2 the capacity of this incinerator would be reduced by approximately 1/8. If the capacity of the incinerator were to be reduced by 2 the approximate dimensions required would have to be 24 inches I.D., 30 inches O.D., 64 inches high.
- 5. At our earliest possible convenience we are to inform HMI what direction the stack should go on the incinerator that is being built. It is my feeling that it should rise vertically rather than have the fast ends.
- 6. Although the project is not mine, and I had no reason other than curiosity to see, I asked to see the incinerators that had been purchased for the evaluation program. A Caloric, Calcinator, Early Morning, were set up and a Wincinator was being assembled.

 af the three previous units the Early Morning appeared to have the highest burning rate.

int	•	

SHAFET-

CONFIDENCIAL

25X1

25X1

Sanitized Copy Approved for Release 2011/09/21 : CIA-RDP78-03642A000600070027-9

	- ONLY		CONFINENTIAL SECRET
IR IECT 10 11	ROUTING AN	ID RECOR	RD SHEET
BJECT: (Optional)			
1	20		
Chief, Physical Se	curity Division	0.5	NO.
Room 1416 - Eye Bu	ilding	-, -	DATE
10thern duty it			2 5 AUG 1959
: (Officer designation, room number, and ding)	DATE	OFFICER'S	
-	RECEIVED FORWARD	IMITIALE	COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)
Unier, Engineering Div.	1000/09 26	100	2 4-44
Room 210	103 345 aug	· WC	seems G Mc
			that an evaluation
	260		report should be used
			and the state of
			La oute par
		†	Techan angettine de les
			Security what our fight
		 	
			goal will be
		 	26aug
		 	The evaluation
			report is underwar to
			report is underway to being completed.
			very completed
			- 7
			FILE: ED1788 Destructor Systems, File
			Dechuster Systems
,			File
			l
			i
			1.